

bmw x5 3.0i auto sport 086434 milleage (5,200 GBP)



Location **West Midlands, Staffordshire**
<https://www.freeadsz.co.uk/x-165382-z>

bmw x5 3.0i auto sport 086434 milleage, BMW, 5 Series, Black, 2003, 86434, 5 doors, 4X4, Semi-Automatic, Petrol, 2.979, ABS, Alarm, immobiliser, alloy wheels, CD player, central locking, electric mirrors, electric windows, heated seats, power steering, radio, sunroof, airbags, child locks, climate control, cruise control, roof bars, electric seats, parking sensor, spoiler, tracker, tinted windows, FOR SALEBMW X5 3.0I AUTO SPORT (PETROL) hello welcome to the sale of my BMW x5, this vehicle is in very good condition as seen from the pictures and drives really well to , the car does not have any dents in the bodywork or any deep scratches , the front plastic bumper is in good condition just a slight mark on the passenger corner but nothing major ,all the lights work including the xenon headlights. The interior is in good condition but it is black leather and please remember the age of the car , there are no rips in the seats or fag burns just worn slightly, The car comes with an MOT certificate due to expire in June 2016 so plenty of time on that , this car prior to the mot was sat in the garage as we didn't need to run it so a couple of items on the advisory's are because of this, i will give a full list of the advisory's and any problems to the best of my knowledge with the car as this is a genuine sale so you know what your buying , many thanks for your interest , ADVISORY ITEMS ARE :Rear break pads wearing thin,Nearside rear brake disc and offside, worn pitted or scored,not seriously weakend , garage did say that because its been sat and got rust on the disc this is the reason it was an advisory like it says not seriously weakend so a few milles driving and breaking will soon bed them in again,offside front track rod end ball joint dust cover slightly damages but preventing the ingress of dirt, parking break efficiency only just met ,Problems known.The only problem i do know about on this vehicle which i have been to the main dealer about also done endless research about and forum discussions is the head unit , the head unit works fine but just recently when the volume is turned up to a certain point the sound will shut off until its turned down to a lower level and the sound is only coming out of one speaker, i have tried all sorts from what i have been told on the forums but the last thing to do is to replace the head unit at a cost of around £250 this apparently is a common problem with the year of the head unit production, i know some people do not tell you everything about a vehicle when buying so i am trying to be honest and make you aware, the car is a fantastic bit of kit and truly does drive well £5,200.00 ono, Swadlincote, 07043512284. Call: 07043 ... Click to reveal number! Seller is using a privacy number - more