

# BENTLEY CONTINENTAL GT,VOLKSWAGEN TOUAREG,PORSCHE CAYENNE CLOCKS



Location

South West, Isle Of Wight

<https://www.freeadsz.co.uk/x-235061-z>



BENTLEY CONTINENTAL GT, VOLKSWAGEN TOUAREG AND PORSCHE CAYENNE INSTRUMENT CLUSTER REPAIR (2004-2010) \*\*THIS IS A REPAIR SERVICE\*\* £150 The Bentley Continental GT, Volkswagen Touareg, and the Porsche Cayenne Dash failure is quite a common fault. On this type of Odometer it is usually caused by internal components breaking down within the Instrument Cluster. The Bentley Continental GT, Volkswagen Touareg, and the Porsche Cayenne repair is carried out by fully qualified electronics engineers and involves stripping down the Instrument Cluster and replacing internal faulty components to rectify the problem. We do not offer "quick fix" we actually replace the faulty parts with new ones required for the Bentley Continental GT, Volkswagen Touareg and the Porsche Cayenne. Your mileage reading will also stay intact, so there is no need for mileage correction. Your Bentley Continental GT, Volkswagen Touareg, and the Porsche Cayenne Speedo can be repaired at a fraction of the cost compared with the price of purchasing a new one. COMMON ISSUES Digital Dashboard LCD repair Back illumination LED's No sound from speakers Failing warning lights Bentley speedometer problems Flickering Cluster Complete power failure CARS THAT USE THIS INSTRUMENT CLUSTER 2003+ Bentley Continental GTn 2005+ Bentley Continental Flying Spur 2003-2010 GTC Bentley Continental GTC 2002-2010 Volkswagen Touareg 2002--2006 Porsche Cayenne (Type 955) REPAIR PROCEDURE 1. Remove the cluster using the instructions on the website 2. Fill out and print our job form on our web site. If you don't have a printer please write the information manually including your post code on the outside of the box for our reference. 3. Sign the form, cut off the address label and secure to the front of the box. 4. We recommend sending via Royal Mail Special Delivery UK 5. When we have received the cluster and have repaired it, we will call you for payment via telephone WARRANTY AND



BENTLEY CONTINENTAL  
GT,VOLKSWAGEN  
TOUAREG,PORSCHE  
CAYENNE CLOCKS  
<https://www.freeadsz.co.uk/x-2350>



BENTLEY CONTINENTAL  
GT,VOLKSWAGEN  
TOUAREG,PORSCHE  
CAYENNE CLOCKS  
<https://www.freeadsz.co.uk/x-2350>



BENTLEY CONTINENTAL  
GT,VOLKSWAGEN  
TOUAREG,PORSCHE  
CAYENNE CLOCKS  
<https://www.freeadsz.co.uk/x-2350>



BENTLEY CONTINENTAL  
GT,VOLKSWAGEN  
TOUAREG,PORSCHE  
CAYENNE CLOCKS  
<https://www.freeadsz.co.uk/x-2350>



BENTLEY CONTINENTAL  
GT,VOLKSWAGEN  
TOUAREG,PORSCHE  
CAYENNE CLOCKS  
<https://www.freeadsz.co.uk/x-2350>




BENTLEY CONTINENTAL  
GT,VOLKSWAGEN  
TOUAREG,PORSCHE  
CAYENNE CLOCKS  
<https://www.freeadsz.co.uk/x-2350>



BENTLEY CONTINENTAL  
GT,VOLKSWAGEN  
TOUAREG,PORSCHE  
CAYENNE CLOCKS  
<https://www.freeadsz.co.uk/x-2350>



BENTLEY CONTINENTAL  
GT,VOLKSWAGEN  
TOUAREG,PORSCHE  
CAYENNE CLOCKS  
<https://www.freeadsz.co.uk/x-2350>



BENTLEY CONTINENTAL  
GT,VOLKSWAGEN  
TOUAREG,PORSCHE  
CAYENNE CLOCKS  
<https://www.freeadsz.co.uk/x-2350>



BENTLEY CONTINENTAL  
GT,VOLKSWAGEN  
TOUAREG,PORSCHE  
CAYENNE CLOCKS  
<https://www.freeadsz.co.uk/x-2350>

TURN AROUND We offer a Lifetime Warranty (T&C's Apply), usually with a 24 hour turn around by post. We can ship to our Workshop in Waterlooville, Portsmouth. We are able to offer a friendly and reliable service. (24 hour turn only) CONTACT US CARRIED BY: 02392 265986 or 02392 265987. ADDRESS: 20 The Parkway, The Aston Road, Waterlooville, Hampshire. WEBSITE: [www.freeadsz.co.uk](https://www.freeadsz.co.uk) WHAT IS IT!!!! DASH CLUSTER SECURE UNIT IT'S THE ECU. YOUR CAR WILL NOT START. THE MILEAGE WILL BE INCORRECT AND YOU WILL NEED IT REPROGRAMMING. WITH OUR SERVICE WE FIX YOUR OWN UNIT AND THE ECUCODING/MILEAGE