# MERCEDES BENZ A CLASS amp VITO LCD PIXEL INSTRUMENT CLUSTER REPAIR







### Lifetime Warranty

Our "Lifetime Warranty" ensures your repair will be covered for as long as you own your vehicle

Location South West, Isle Of Wight

https://www.freeadsz.co.uk/x-235064-z

MERCEDES BENZ A CLASS & VITO LCD PIXEL INSTRUMENT CLUSTER REPAIR (1999-2004)

£99

On this type of Odometer it is usually caused by internal components breaking down within the Instrument Cluster. The repair is carried out by fully qualified electronics engineers. We strip down the Instrument Cluster and replace internal faulty components to rectify the problem. We do not offer "quick fix" we actually replace the faulty parts with new ones required for the Mercedes. (Your mileage reading will stay intact, so there is no need for mileage correction.) Your Mercedes Speedo can be repaired at a fraction of the cost compared with the price of purchasing a new one COMMON ISSUES

Failing warning lights Speedometer gauge problems Flickering Cluster Complete power failure Pixels failing on screen

#### REPAIR PROCEDURE

1. Remove the cluster using the instructions on the website



MERCEDES amp VITO





https://www.freeadsz.co.uk/x-2350 64-z CD











## CONTACT US

## CARTRONIX

CALL: 02392 265 986 or 02392 241412

ADDRESS: Unit 20The Parkwood Centre, Aston Road, Waterlooville, PO7 7HT

WEBSITE: www.cartronix.co.uk WARNING!!!! DON'T BUY A SECOND HAND UNIT IT IS A FALSE ECONOMY. YOUR CAR WILL NOT START. THE MILEAGE WILL BE INCORRECT AND YOU WILL

NEED IT PROGRAMMING!!!

WITH OUR SERVICE WE FIX YOUR OWN UNIT AND THE CODING/MILEAGE REMAINS.