


Audi 80 1994 2.0e Sport (400 GBP)



Location

South East, Berkshire
<https://www.freeadsz.co.uk/x-238104-z>


Audi 80 Sport 2.0E Saloon
1994 on M reg

172000 miles but will rise as its in daily use

Genuine sport with sports steering wheel/seats/spoiler etc, all original with no aftermarket parts fitted at all. It is in a pretty good condition considering its 20 years old, some dents/scratches but nothing too serious. The interiors in good condition too, with a little wear to the carpets and drivers seat bolster. Its in mechanically in good condition, it has never let me down, and I was considering taking it on our annual trip to Germany we do. With these having a galvanised chassis there is no major rust anywhere, except the small patch on the front wing. It has uprated pioneer front dash speakers and 6x9s that a previous owner cut into the rear doors and a Sony radio with aux in/cd/radio. There was no service history when I got it, just the most recent MOT certificate, which expires 29/05/2016. The only advisory on the last were wheel bearings on the rear, not expensive or difficult to change. All in all its a very honest car which with a days work it would be a fantastic daily or project.

When I got the car it had many problems which were not described which I've fixed:

I gave the car a full oil and filter change, new plugs, new fuel and cabin filters

when I got it the temp gauge wasn't working, so to fix it I've given it a full coolant flush and change, a new thermostat and radiator, and new temp sensors.

The fuel and temperature gauges are now fully working

fixed dodgy wiring going from car into bootlid
had to take the bootlid off to allow some
loose wires to be sorted

fixed fuel pump
clicking noise when turning on full lock sometimes, suspected cv joint but not had time to investigate

the exhaust is knocking on the rear and just needs adjusting I would have thought

https://www.freeadsz.co.uk/x-238104-z

Audi 80 1994 2.0e Sport

located in Horsham/West Sussex RH1

the audi now has a radio. the original key has snapped in half therefore will need trailering/towing away. It


also has been SCORNed as its no longer needed as its replacement is.

<https://www.freeadsz.co.uk/x-238104-z>

Audi 80 1994 2.0e Sport



<https://www.freeadsz.co.uk/x-238104-z>
Audi 80 1994 2.0e Sport



<https://www.freeadsz.co.uk/x-238104-z>
Audi 80 1994 2.0e Sport




<https://www.freeadsz.co.uk/x-238104-z>
Audi 80 1994 2.0e Sport



<https://www.freeadsz.co.uk/x-238104-z>
Audi 80 1994 2.0e Sport




<https://www.freeadsz.co.uk/x-238104-z>
Audi 80 1994 2.0e Sport




<https://www.freeadsz.co.uk/x-238104-z>
Audi 80 1994 2.0e Sport




<https://www.freeadsz.co.uk/x-238104-z>
Audi 80 1994 2.0e Sport



<https://www.freeadsz.co.uk/x-238104-z>
Audi 80 1994 2.0e Sport



<https://www.freeadsz.co.uk/x-238104-z>
Audi 80 1994 2.0e Sport



<https://www.freeadsz.co.uk/x-238104-z>
Audi 80 1994 2.0e Sport