

AUDI TT MK1 INSTRUMENT CLUSTER SPEEDO REPAIR (1998-2006)



Lifetime Warranty

Our "Lifetime Warranty" ensures your repair will be covered for as long as you own your vehicle.

Location


South East, West Sussex

<https://www.freedasz.co.uk/x-296344-z>



Audi Tt Mk1 Instrument Cluster Repair (1998-2006) £120- £150 COMMON ISSUES The Audi TT Mk1 Dash failure is quite a common fault. On this type of Odometer the fault is usually caused by internal components breaking down within the Instrument Cluster. The AUDI TT MK1 repair is carried out by fully qualified electronics engineers which involves stripping down the Instrument Cluster and replacing internal faulty components to rectify the problem. We do not offer "quick fix" we actually replace the faulty parts with new ones required for the AUDI TT MK1. Your mileage reading will also stay intact so there is no need for mileage correction. Your AUDI TT MK1 Speedo can be repaired at a fraction of the cost compared with the price of purchasing a new one COMMON ISSUES Mileage showing 999,999 miles Gauges reading incorrect readings Failing warning lights Speedometer problems Flickering Cluster Complete power failure Warning buzzer failure. **** For Pixels failing on screen see our other listing for LCD Replacement **** REPAIR PROCEDURE 1. Remove the cluster using the instructions on the website 2. Fill out and print our job form on our web site. If you don't have a printer please write the information manually including your post code on the outside of the box for our reference. 3. Sign the form, cut off the address label and secure to the front of the box. 4. We recommend sending via Royal Mail Special Delivery UK 5. When we have received the cluster and have repaired it, we will call you for payment via telephone WARRANTY AND TURN AROUND We offer a Lifetime Warranty (T&C's Apply), usually with a 24 hour turn around by post. If you come to our workshop in Waterlooville (near Portsmouth) we are able to offer a friendly 90 minute fast track service. (Appointment only) CONTACT US CARTRONIX CALL: 02392 265 986 or 02392 241412 ADDRESS: Unit 20 The Parkwood Centre, Aston Road, Waterlooville, PO7 7HT Website: www.cartronix.co.uk WARNING!!!! DON'T BUY A SECOND

HAND UNIT IT IS A FALSE ECONOMY YOUR CAR WILL NOT START. THE MILEAGE WILL BE INCREASED AND YOU WILL NEED TO REPROGRAMM YOUR SEVERAL MILES TO FIX YOUR PROBLEM THE COST OF MILEAGE REPAIR IS



AUDI TT MK1 INSTRUMENT
CLUSTER SPEEDO REPAIR
(1998-2006)

<https://www.freedasz.co.uk/x-296344-z>



AUDI TT MK1 INSTRUMENT
CLUSTER SPEEDO REPAIR
(1998-2006)

<https://www.freedasz.co.uk/x-296344-z>



AUDI TT MK1 INSTRUMENT
CLUSTER SPEEDO REPAIR
(1998-2006)

<https://www.freedasz.co.uk/x-296344-z>



AUDI TT MK1 INSTRUMENT
CLUSTER SPEEDO REPAIR
(1998-2006)

<https://www.freedasz.co.uk/x-296344-z>



AUDI TT MK1 INSTRUMENT
CLUSTER SPEEDO REPAIR
(1998-2006)

<https://www.freedasz.co.uk/x-296344-z>



AUDI TT MK1 INSTRUMENT
CLUSTER SPEEDO REPAIR
(1998-2006)

<https://www.freedasz.co.uk/x-296344-z>



AUDI TT MK1 INSTRUMENT
CLUSTER SPEEDO REPAIR
(1998-2006)

<https://www.freedasz.co.uk/x-296344-z>




AUDI TT MK1 INSTRUMENT
CLUSTER SPEEDO REPAIR
(1998-2006)

<https://www.freedasz.co.uk/x-296344-z>



AUDI TT MK1 INSTRUMENT
CLUSTER SPEEDO REPAIR
(1998-2006)

<https://www.freedasz.co.uk/x-296344-z>



AUDI TT MK1 INSTRUMENT
CLUSTER SPEEDO REPAIR
(1998-2006)

<https://www.freedasz.co.uk/x-296344-z>