

VOLKSWAGEN POLO INSTRUMENT CLUSTER DASH SPEEDO CLOCKS REPAIR



Location South East, West Sussex https://www.freeadsz.co.uk/x-296348-z

VOLKSWAGEN POLO INSTRUMENT CLUSTER REPAIR (1997-2006) £99


The Volkswagen Polo Dash failure is quite a common fault. On this type of Odometer it is usually caused by internal components breaking down within the Instrument Cluster. The repair is carried out by fully qualified electronics engineers which involves stripping down the Instrument Cluster and replacing internal faulty components to rectify the problem. We do not offer "quick fix" we actually replace the faulty parts with new ones required. Your mileage reading will also stay intact, so there is no need for mileage correction.

Your VW Speedo can be repaired at a fraction of the cost compared with the price of purchasing a new one. COMMON ISSUES

Failing warning lightsSpeedometer problemsFlickering clusterComplete power failurePixels failing on sreen

REPAIR PROCEDURE

1. Remove the cluster using the instructions on the website



CONTACT US

CARTRONIX

CALL: 02392 265 986 or 02392 241412 ADDRESS: Unit 20 The Parkwood Centre, Aston Road, Waterlooville, PO7 7HT WEBSITE: www.cartronix.co.uk WARNING!!!! DON'T BUY A SECOND HAND UNIT IT IS A FALSE ECONOMY. YOUR CAR WILL NOT START. THE MILEAGE WILL BE INCORRECT AND YOU WILL NEED IT PROGRAMMING!!! WITH OUR SERVICE WE FIX YOUR OWN UNIT AND THE CODING/MILEAGE REMAINS.