

Audi A4 2007 (3,800 GBP)



Location **West Midlands, Herefordshire**
<https://www.freeadsz.co.uk/x-330273-z>

Audi 2007 S- Line Quattro in Black with a full leather interior. The car has been in the family since the 2nd owner and has been very well looked after with only expected signs of wear and tear.










I have decided to peruse a career overseas and will soon no longer need the vehicle.

The car has recently had new tyres fitted & comes with the roof bars. The cambelt has already been changed.

The car is in overall very good condition. Many of the miles are made up of motorway miles and the high mileage doesn't effect car's performance.

The car has been triggering a engine management light fault for the last 6 months - Running to lean at idle (Not ticking over at high enough revs when idle) . I have had several Audi specialists diagnose the car, and they have said the car is running correctly at idle and to ignore the light.

In pursuit of turing the light of I have spent in excess of £500 by changing the following parts (including part number). I have also had several other valves and parts changed, and will update the Add when the Garage gets back to me with old invoices.

 https://www.freeadsz.co.uk/x-330273-z <div>AudiA42007</div>	 https://www.freeadsz.co.uk/x-330273-z <div>AudiA42007</div>	 https://www.freeadsz.co.uk/x-330273-z <div>AudiA42007</div>	 https://www.freeadsz.co.uk/x-330273-z <div>AudiA42007</div>	<div>1.06F-133-781L - Check Valve With Pipes 2.06F-133-781R - 3.06F-133-781F Ignition Coil 2nd Ignition 4.06F-133-781G Ignition Coil 1st Ignition 5.06F-133-781H Ignition Coil 2nd Ignition 6.06F-133-781J Ignition Coil 1st Ignition 7.06F-133-781K Ignition Coil 2nd Ignition 8.06F-133-781L Ignition Coil 1st Ignition 9.06F-133-781M Ignition Coil 2nd Ignition 10.06F-133-781N Ignition Coil 1st Ignition 11.06F-133-781P Ignition Coil 2nd Ignition 12.06F-133-781Q Ignition Coil 1st Ignition 13.06F-133-781R Ignition Coil 2nd Ignition 14.06F-133-781S Ignition Coil 1st Ignition 15.06F-133-781T Ignition Coil 2nd Ignition 16.06F-133-781U Ignition Coil 1st Ignition 17.06F-133-781V Ignition Coil 2nd Ignition 18.06F-133-781W Ignition Coil 1st Ignition 19.06F-133-781X Ignition Coil 2nd Ignition 20.06F-133-781Y Ignition Coil 1st Ignition 21.06F-133-781Z Ignition Coil 2nd Ignition</div>  https://www.freeadsz.co.uk/x-330273-z <div>AudiA42007</div>	<div>Both garages have advised me to ignore the fault as I have been spending money on trying to fix something that isn't broken. After test drives and inspections!</div>  https://www.freeadsz.co.uk/x-330273-z <div>AudiA42007</div>	 https://www.freeadsz.co.uk/x-330273-z <div>AudiA42007</div>	 https://www.freeadsz.co.uk/x-330273-z <div>AudiA42007</div>	 https://www.freeadsz.co.uk/x-330273-z <div>AudiA42007</div>	 https://www.freeadsz.co.uk/x-330273-z <div>AudiA42007</div>
--	---	---	---	--	--	---	---	---	---