

royale cooker ry50sew ,spare or repair (35 GBP)



Location **Scotland, Strathclyde**
<https://www.freeadsz.co.uk/x-334545-z>



royale cooker ry50sew ,spare or repair .

*The right rear element need replacing and it'll cost £24.00 on average for a new element .

*The control panel indicators are rubbed off / worn off . see photos . I was trying to use sticky clear paper and make a temple indicator .

* I got the hob in my house and I'll test , the r/ rear hob in later on tonight to see , if she's working .

* it's been out in my garage , for 3 months sealed in shink wrap and It was fully working and thoroughly cleaned up and out , before storage ? . I have to do an electrical check on her . If , you buy the parts , for her I'll install them for.




royale cooker ry50sew ,spare
or
repair

<https://www.freeadsz.co.uk/x-334545-z>



royale cooker ry50sew ,spare
or
repair

<https://www.freeadsz.co.uk/x-334545-z>



royale cooker ry50sew ,spare
or
repair

<https://www.freeadsz.co.uk/x-334545-z>



royale cooker ry50sew ,spare
or
repair

<https://www.freeadsz.co.uk/x-334545-z>



royale cooker ry50sew ,spare
or
repair

<https://www.freeadsz.co.uk/x-334545-z>



royale cooker ry50sew ,spare
or
repair

<https://www.freeadsz.co.uk/x-334545-z>



royale cooker ry50sew ,spare
or
repair

<https://www.freeadsz.co.uk/x-334545-z>




royale cooker ry50sew ,spare
or
repair

<https://www.freeadsz.co.uk/x-334545-z>



royale cooker ry50sew ,spare
or
repair

<https://www.freeadsz.co.uk/x-334545-z>



royale cooker ry50sew ,spare
or
repair

<https://www.freeadsz.co.uk/x-334545-z>