











Suzuki TS50 1998 (800 GBP)



Location **South East, Kent**
<https://www.freeadsz.co.uk/x-409674-z>



1998 Suzuki TS50 with 18K showing on the clocks. Engine has just been rebuilt with new Crank, bearings, oil seals and a 49CC barrel and piston kits. Very clean bike for its age. Only defects worth mentioning are a couple of small cigaret burns at the back of the seat and some deep cuts / scratches on the front plastic mud guard. Also the oil pump which adds oil to the fuel on a two stroke engine isn't working properly so I am pre-mixing the oil into the fuel when filling the tank. Would recommend new owner do the same as the pumps are difficult to come by. Ideal as a first bike as due to the low power output, but it can be boosted when the new rider has some more experience with a 70cc barrel and piston and or a less restrictive exhaust.

 <div>Suzuki TS50 1998 https://www.freeadsz.co.uk/x-409674-z</div>	 <div>Suzuki TS50 1998 https://www.freeadsz.co.uk/x-409674-z</div>	 <div>Suzuki TS50 1998 https://www.freeadsz.co.uk/x-409674-z</div>	 <div>Suzuki TS50 1998 https://www.freeadsz.co.uk/x-409674-z</div>	 <div>Suzuki TS50 1998 https://www.freeadsz.co.uk/x-409674-z</div>	 <div>Suzuki TS50 1998 https://www.freeadsz.co.uk/x-409674-z</div>	 <div>Suzuki TS50 1998 https://www.freeadsz.co.uk/x-409674-z</div>	 <div>Suzuki TS50 1998 https://www.freeadsz.co.uk/x-409674-z</div>	 <div>Suzuki TS50 1998 https://www.freeadsz.co.uk/x-409674-z</div>	 <div>Suzuki TS50 1998 https://www.freeadsz.co.uk/x-409674-z</div>
--	---	---	---	--	---	---	---	---	---