











Ford Mondeo ST220 3.0 V6 Fully Loaded (1,800 GBP)



Location **South West, Hampshire**
<https://www.freeadsz.co.uk/x-429449-z>

Reluctant sale of my high spec St220. 6 speed manual, Climate control, Touch screen, CD multi changer and aux input, Heated full electric recaro seats, Auto dimming rear view mirror, Xenon headlights from factory, Heated windscreen, Auto front and rear wiper, Auto headlights with headlight washers, Electric windows and mirrors, Top level media package, Electronic Stability Program, fully loaded car from factory. one of the last to have a 6 speed gearbox yet be early enough to be in the cheap tax category before laws changed, car does have small age related marks (one kerbed alloy and stone chips on front bumper) but is very well looked after and has always been regularly serviced, genuine reason for sale is I don't get the use out of it that I'd like to, the car drives lovely and has a straight through cat back exhaust system, it is loud but sounds the way a V6 should, also has an aftermarket induction kit fitted however I do still have the standard airbox. mileage is approx 135k miles, may rise slowly as it is still used occasionally, only other note is that the cars built in satnav does not work, I purchased the car with this fault after the car sales office I bought it from failed to rectify it when asked and told me it needed a sat nav update dvd which I bought and updated however this did not remedy the problem, I have recently had the car looked at and it was concluded that it needs a roof aerial, an easy fix and a cheap part (found new online for around £40) however I never bothered as I no longer travel far enough to require a satnav, it has also just come to my attention that the passenger side headlight washer isn't operating, I can't be 100% as to whether it has ever worked however they are only water pressure operated so I suspect it only needs a washer telescope, I have been as honest as possible with this advert so if you have any questions please ask. Advertised on other.

 <p>Ford Mondeo ST220 3.0 V6 Fully Loaded</p> <p>https://www.freeadsz.co.uk/x-4294</p>	 <p>Ford Mondeo ST220 3.0 V6 Fully Loaded</p> <p>https://www.freeadsz.co.uk/x-4294</p>	 <p>Ford Mondeo ST220 3.0 V6 Fully Loaded</p> <p>https://www.freeadsz.co.uk/x-4294</p>	 <p>Ford Mondeo ST220 3.0 V6 Fully Loaded</p> <p>https://www.freeadsz.co.uk/x-4294</p>	 <p>Ford Mondeo ST220 3.0 V6 Fully Loaded</p> <p>https://www.freeadsz.co.uk/x-4294</p>	 <p>Ford Mondeo ST220 3.0 V6 Fully Loaded</p> <p>https://www.freeadsz.co.uk/x-4294</p>	 <p>Ford Mondeo ST220 3.0 V6 Fully Loaded</p> <p>https://www.freeadsz.co.uk/x-4294</p>	 <p>Ford Mondeo ST220 3.0 V6 Fully Loaded</p> <p>https://www.freeadsz.co.uk/x-4294</p>	 <p>Ford Mondeo ST220 3.0 V6 Fully Loaded</p> <p>https://www.freeadsz.co.uk/x-4294</p>	 <p>Ford Mondeo ST220 3.0 V6 Fully Loaded</p> <p>https://www.freeadsz.co.uk/x-4294</p>
--	---	---	---	--	---	---	---	---	---