











Honda VFR 750 (1,750 GBP)



Location **South West, Avon**
<https://www.freeadsz.co.uk/x-429873-z>



Recent fluids change factory pro detent arm for smoother gear changes fairly new seat, full exhaust and battery led instrument panel mot Til April 17' some damage due to stationary fall at petrol station loads of tread left on tyres pearlescent white recent carb clean and balance upjetted with factory pro kit k and n air filter new starter clutch no oil or fork leaks adjustable levers very comfortable sports tourer riding position hi level exhaust simply don't get out on it enough and I have an old fireblade for the odd weekend out Any questions just ask ;

 <div><div>Honda</div><div>VFR</div><div>750</div></div> <div>https://www.freeadsz.co.uk/x-429873-z</div>	 <div><div>Honda</div><div>VFR</div><div>750</div></div> <div>https://www.freeadsz.co.uk/x-429873-z</div>	 <div><div>Honda</div><div>VFR</div><div>750</div></div> <div>https://www.freeadsz.co.uk/x-429873-z</div>	 <div><div>Honda</div><div>VFR</div><div>750</div></div> <div>https://www.freeadsz.co.uk/x-429873-z</div>	 <div><div>Honda</div><div>VFR</div><div>750</div></div> <div>https://www.freeadsz.co.uk/x-429873-z</div>	 <div><div>Honda</div><div>VFR</div><div>750</div></div> <div>https://www.freeadsz.co.uk/x-429873-z</div>	 <div><div>Honda</div><div>VFR</div><div>750</div></div> <div>https://www.freeadsz.co.uk/x-429873-z</div>	 <div><div>Honda</div><div>VFR</div><div>750</div></div> <div>https://www.freeadsz.co.uk/x-429873-z</div>	 <div><div>Honda</div><div>VFR</div><div>750</div></div> <div>https://www.freeadsz.co.uk/x-429873-z</div>	 <div><div>Honda</div><div>VFR</div><div>750</div></div> <div>https://www.freeadsz.co.uk/x-429873-z</div>
---	--	--	--	---	--	--	--	--	--