## Lewmar Pro-Fish 1000 Windlass for 516quot Chain, Working but Needs TLC. (60 GBP)



South East, West Sussex Location https://www.freeadsz.co.uk/x-462438-z



This is the more powerful version of the two Pro-Fish windlasses from Lewmar, fitted with a 5/16" chain gipsy, made of solid stainless steel except for the gipsy, which is bronze. (RRP for these is over £900.) It was installed on a charter yacht and had been in a jammed up condition, with the chain guide so bent that the motor would not turn the chain gipsy. With the help of the Lewmar works in Havant, it has been stripped down and cleaned and all working parts greased before reassembly. The motor now turns the gipsy as it should, but the chain guide really needs to be replaced, as do a number of PTFE washers/bearings (ebay) and the pin which disengages the drive to the gipsy for the freefall facility. All these parts are available from ebay or Lewmar. The three studs for bolting it down are included, but the rubber gasket is too flattened to be useful. Selling as I now have a more suitable windlass for my boat. Asking £60 ovno.

Buyer collects or I could deliver in the Portsmouth area at fuel cost, or send by parcel2go carrier, which will be around &pound.







//wwv	ewmar lass f	
v.free	but	
//www.freeadsz.co.uk/x-4624	Pro-Fish 516quot Needs	
/x-4624	1000 Chain, TLC.	



ps://www.freeadsz.co	Lewmar indlass 1 orking	
/.free	ör	
adsz.cc	Pro-Fi; 516qu Nee	





-z ps://wwv	Lewmar indlass f orking
v.free	ar for but
ps://www.freeadsz.co.uk/x-46 -z	Pro-Fish 516quot Needs
/x-46	다. 다.



nttps://www.freeadsz.co.uk	Lewmar Windlass f Working I
/.free	out or _
adsz.co.uk	Pro-Fish 516quot Needs



tps://wwv 8-z	orking/
v.freea	but
tps://www.freeadsz.co.uk/x-4624 3-z	orking but Needs TLC
(-4624	TLC





http://www.frooder.co	Working	Windlass	Lewmai
•	but	<u>o</u>	¥
7		516au	Pro-Fi
3	8 -	Ħ.	<u>;;</u> !

https://www	Working
v.freea	but
.ttps://www.freeadsz.co.uk/x-4624 i8-z	Needs
(-4624	TLC

Pro-Fish



https://www.fr 38-z	Windlass Working
/.fr	ᇰᄼ

orking	indlass	Lewma
but	for	=
Need	516quc	Pro-Fisl

