



Our "Lifetime Warranty" ensures your repair will be covered for as long as you own your vehicle.

PEUGEOT BOXER 2 INSTRUMENT CLUSTER REPAIR (2007-)
£150

The Peugeot Boxer Dash failure is quite a common fault. On this type of Odometer it is usually caused by internal components breaking down within the Instrument Cluster. The repair is carried out by fully qualified electronics engineers which involves stripping down the Instrument Cluster and replacing internal faulty components to rectify the problem. We do not offer "quick fix" we actually replace the faulty parts with new ones required.. Your mileage reading will also stay intact, so there is no need for mileage correction.

Your Peugeot Speedo can be repaired at a fraction of the cost compared with the price of purchasing a new one. **COMMON ISSUES**

Failing warning lightsSpeedometer problemsFlickering clusterComplete power failurePixels failing on screen

REPAIR PROCEDURE

1. Remove the cluster using the instructions on the website
2. Fill out and print our job form on our web site. If you don't have a printer please write the information

manually including your post code on the outside of the box for our reference

3. Stop the farm, cut off the address lane and secure to the front of the box

4. We recommend that the Royal Mail special Deliver work

57 When we have received your cluster, we have repaired it. We will call you for payment via telephone.

WARRANTY AND REMEDY FOUND

We offer a Lifetime Warranty (T&C's Apply, usually with a 24-hour turn around by post).

If you come to our workshop in Waterlooville (near Portsmouth) we are able to offer a friendly 90 minute fast track service. (Appointment only)

CONTACT US



PEUGEOT	BOXER	2
STRUMENT	CLUSTER	
SH	SPEEDO	CLOCKS
PAIR		



PEUGEOT BOXER 2
INSTRUMENT CLUSTER
DASH SPEEDO CLOCKS
REPAIR


<https://www.freadsz.co.uk/x-2147>

67-z



PEUGEOT BOXER 2
INSTRUMENT CLUSTER
DASH SPEEDO CLOCKS
REPAIR

<https://www.freedsz.co.uk/x-2147>
67-2



PEUGEOT BOXER 2
INSTRUMENT CLUSTER
DASH SPEEDO CLOCKS
REPAIR

<https://www.freedsz.co.uk/x-2147>
67-z




CONTACT US
If you come to
fast track service
offer
REPAIRS
DASH SPEEDO
INSTRUMENT
PEGGOT BOXER
CLUSTER
CLOCK
CLUSTER
CLOCK
2



<https://www.beadsz.co.uk/x-2147760z>



<https://www.freedasz.co.uk/x-2147>
 6x-2



with a 24-hour turnaround time. The repair is done in-house, so you can get your instrument back in the lab as quickly as possible. For more information, visit www.freedasz.co.uk/x-214765-z.



<https://www.freedesktop.org/wiki/Software/FreeRDP/>



90 minute
https://www.freeadsz.co.uk/x-2147
67-z

CARTRONIX

CALL: 02392 265 986 or 02392 241412 ADDRESS: Unit 20 The Parkwood Centre, Aston Road,
Waterlooville, PO7 7HT WEBSITE: www.cartronix.co.uk WARNING!!!! DON'T BUY A SECOND HAND
UNIT IT IS A FALSE ECONOMY. YOUR CAR WILL NOT START. THE MILEAGE WILL BE INCORRECT
AND YOU WILL NEED IT PROGRAMMING!!!
WITH OUR SERVICE WE FIX YOUR OWN UNIT AND THE CODING/MILEAGE REMAINS.