

RANGE ROVER L322 MID RADIO OBC LCD PIXEL REPAIR



Lifetime Warranty

Our "Lifetime Warranty" ensures your repair will be covered for as long as you own your vehicle.

Location

<https://www.freeadsz.co.uk/x-235059-z>

South West, Isle Of Wight

LCD Repair for RANGE ROVER L322 £99 We repair the LCD display on OBC & Mid Radios. If you have missing pixels or your display is unreadable we can help. We replace the faulty components with OEM parts sourced by ourselves. The repair is carried out by fully qualified electronics engineers which involves stripping down the unit and replacing the faulty parts.

COMMON ISSUES Missing Pixels Corrupt LCD

REPAIR PROCEDURE

1. Remove the cluster using the instructions on the site
2. Fill out and print our job form at www.cartronix.co.uk. If you don't have a printer please write out the information manually and put it in the box with the cluster.
3. Sign the form, cut off the Address Label and secure to the outside of the box.
4. We recommend sending via Royal Mail Special Delivery
5. When we receive the unit, we will carry out the repair and call you for payment over the phone.

Warranty and Turn Around

We offer a Lifetime Warranty (T&C's Apply), usually with 24 Hour turn around by post. We also have a 90 minute fast track service if you come to our workshop in Waterlooville near Portsmouth. (Appointment only)

Contact Us

RANGE ROVER L322 MID RADIO OBC LCD PIXEL REPAIR https://www.freeadsz.co.uk/x-235059-z	RANGE ROVER L322 MID RADIO OBC LCD PIXEL REPAIR https://www.freeadsz.co.uk/x-235059-z	RANGE ROVER L322 MID RADIO OBC LCD PIXEL REPAIR https://www.freeadsz.co.uk/x-235059-z	RANGE ROVER L322 MID RADIO OBC LCD PIXEL REPAIR https://www.freeadsz.co.uk/x-235059-z	RANGE ROVER L322 MID RADIO OBC LCD PIXEL REPAIR https://www.freeadsz.co.uk/x-235059-z	RANGE ROVER L322 MID RADIO OBC LCD PIXEL REPAIR https://www.freeadsz.co.uk/x-235059-z	RANGE ROVER L322 MID RADIO OBC LCD PIXEL REPAIR https://www.freeadsz.co.uk/x-235059-z	RANGE ROVER L322 MID RADIO OBC LCD PIXEL REPAIR https://www.freeadsz.co.uk/x-235059-z	RANGE ROVER L322 MID RADIO OBC LCD PIXEL REPAIR https://www.freeadsz.co.uk/x-235059-z	RANGE ROVER L322 MID RADIO OBC LCD PIXEL REPAIR https://www.freeadsz.co.uk/x-235059-z	RANGE ROVER L322 MID RADIO OBC LCD PIXEL REPAIR https://www.freeadsz.co.uk/x-235059-z	RANGE ROVER L322 MID RADIO OBC LCD PIXEL REPAIR https://www.freeadsz.co.uk/x-235059-z	RANGE ROVER L322 MID RADIO OBC LCD PIXEL REPAIR https://www.freeadsz.co.uk/x-235059-z	RANGE ROVER L322 MID RADIO OBC LCD PIXEL REPAIR https://www.freeadsz.co.uk/x-235059-z



RANGE ROVER L322 MID RADIO OBC LCD PIXEL REPAIR
<https://www.freeadsz.co.uk/x-235059-z>