



Our "Lifetime Warranty" ensures your repair will be covered for as long as you own your vehicle.

<https://www.freeadsz.co.uk/x-235061-z>

**BENTLEY CONTINENTAL GT, VOLKSWAGEN TOUAREG AND PORSCHE CAYENNE INSTRUMENT CLUSTER REPAIR (2004-2010) \*\*THIS IS A REPAIR SERVICE\*\* £150** The Bentley Continental GT, Volkswagen Touareg, and the Porsche Cayenne Dash failure is quite a common fault. On this type of Odometer it is usually caused by internal components breaking down within the Instrument Cluster. The Bentley Continental GT, Volkswagen Touareg, and the Porsche Cayenne repair is carried out by fully qualified electronics engineers and involves stripping down the Instrument Cluster and replacing internal faulty components to rectify the problem. We do not offer "quick fix" we actually replace the faulty parts with new ones required for the Bentley Continental GT, Volkswagen Touareg and the Porsche Cayenne. Your mileage reading will also stay intact, so there is no need for mileage correction. Your Bentley Continental GT, Volkswagen Touareg, and the Porsche Cayenne Speedo can be repaired at a fraction of the cost compared with the price of purchasing a new one. **COMMON ISSUES** Digital Dashboard LCD repair Back illumination LED's No sound from speakers Failing warning lights Bentley speedometer problems Flickering Cluster Complete power failure **CARS THAT USE THIS INSTRUMENT CLUSTER** 2003+ Bentley Continental GTn 2005+ Bentley Continental Flying Spur 2003-2010 GTC Bentley Continental GTC 2002-2010 Volkswagen Touareg 2002--2006 Porsche Cayenne (Type 955) **REPAIR PROCEDURE** 1. Remove the cluster using the instructions on the website 2. Fill out and print our job form on our web site. If you don't have a printer please write the information manually including your post code on the outside of the box for our reference. 3. Sign the form, cut off the address label and secure to the front of the box. 4. We recommend sending via Royal Mail Special Delivery UK 5. When we have received the cluster and have repaired it, we will call you for payment via telephone **WARRANTY AND**

TURN AROUND! We offer a Lifetime Warranty (T&C's Apply), usually with a 24 hour turn around by post  
 if you come to our workshop. Waterloo, Victoria, Port Phillip. We are able to offer a friendly service at the  
 best price service. (Astonishingly only) OCM TAC - US CARTER. CALL: 02-952-265006 or 02-952-  
 265002. ADDRESS: 111-113 Parkview, Ashford, Astoria, New Waterlooville. WWW.OCM.TAC.CO.UK  
 WWW.OCM.TAC.CO.UK. DONT LET A SECOND HAND UNIT IN YOUR CAR BE ECONOMY  
 YOUR CAR WILL NOT START! THE MILEAGE WILL BE INCORRECT AND YOU WILL NEED IT  
 PROGRAMMING WITH YOUR SERVICE WE FIX YOUR OWN UNIT AND THE CODING/MILEAGE



BENTLEY CONTINENTAL  
GT,VOLKSWAGEN  
TOUAREG,PORSCHE  
CAYENNE CLOCKS  
<https://www.freedasz.co.uk/x-2350>



BENTLEY CONTINENTAL  
GT,VOLKSWAGEN  
TOUAREG,PORSCHE  
CAYENNE CLOCKS  
<https://www.freedsz.co.uk/x-2350>  
61-z




BENTLEY CONTINENTAL  
GT,VOLKSWAGEN  
TOUAREG,PORSCHE  
CAYENNE CLOCKS  
<https://www.freeadsz.co.uk/x-2350>  
61-z



**BENTLEY CONTINENTAL  
GT,VOLKSWAGEN  
TOUAREG,PORSCHE  
CAYENNE CLOCKS**  
<https://www.freeadsz.co.uk/x-235061-z>



PROGRAMME  
CONTINENTAL  
VOLKSWAGEN  
TOUAREG, PORSCHE  
CAYENNE  
CLOCKSS




BRENNLEY CONTINENTAL  
 GT VOLKSWAGEN  
 SQUARE, PORSCHE  
 CAYENNE CLOCKS  
<https://www.freedasz.co.uk/x-2350>  
 67:z



**R**Y  
**C**L  
**O**C  
**K**S  
**E**V  
**E**N  
**T**A  
67z



OWN UNIT  
ST. VOLKSWAGEN  
TUA REG, PORSCHE  
AYENNE CLOCKS  
<https://www.freeadsz.co.uk/x-2350>  
dz



CODIN  
 CONTINENTAL  
 BUNILE  
 VOLKSWAGEN  
 SQUARE, PORSCHE  
 CAYENNE  
 CLOCKS  
 https://www.freedatsz.co.uk/x-2350  
 61-z



BENILEY CONTINENTAL  
 GT.VOLKSWAGEN  
 TOUTAREG,PORSCH  
 HYENNE CLOCKS  
 https://www.freedasz.co.uk/x-2350  
 617z