

MERCEDES BENZ A CLASS amp VITO LCD PIXEL INSTRUMENT CLUSTER REPAIR



Lifetime Warranty

Our "Lifetime Warranty" ensures your repair will be covered for as long as you own your vehicle.

Location

South West, Isle Of Wight

<https://www.freeadsz.co.uk/x-235064-z>



MERCEDES BENZ A CLASS & VITO LCD PIXEL INSTRUMENT CLUSTER REPAIR (1999-2004)

£99

On this type of Odometer it is usually caused by internal components breaking down within the Instrument Cluster. The repair is carried out by fully qualified electronics engineers. We strip down the Instrument Cluster and replace internal faulty components to rectify the problem. We do not offer "quick fix" we actually replace the faulty parts with new ones required for the Mercedes. (Your mileage reading will stay intact, so there is no need for mileage correction.) Your Mercedes Speedo can be repaired at a fraction of the cost compared with the price of purchasing a new one **COMMON ISSUES**

Failing warning lights
Speedometer gauge problems
Flickering Cluster
Complete power failure
Pixels failing on screen

REPAIR PROCEDURE

1. Remove the cluster using the instructions on the website

2. Fill out and print our job form on our web site. If you don't have a printer please write the information on a piece of paper including a photo of the back of the cluster and send it to us by post. 3. We will send you a return form, cut out the address label and stick it on the back of the box. 4. We will send you a Royal Mail tracked delivery box. 5. We will have repaired your cluster and sent it back to you via the Royal Mail via tele.

WARRANTY AND TURN AROUND

We offer a Lifetime Warranty (T&C's Apply), usually with a 24-hour turn around by post.

If you come to our workshop in Waterlooville (near Portsmouth) we are able to offer a friendly 90-minute fast track service. (Appointment only)



MERCEDES BENZ A CLASS
amp VITO LCD PIXEL
INSTRUMENT CLUSTER
REPAIR
<https://www.freeadsz.co.uk/x-235064-z>



MERCEDES BENZ A CLASS
amp VITO LCD PIXEL
INSTRUMENT CLUSTER
REPAIR
<https://www.freeadsz.co.uk/x-235064-z>



MERCEDES BENZ A CLASS
amp VITO LCD PIXEL
INSTRUMENT CLUSTER
REPAIR
<https://www.freeadsz.co.uk/x-235064-z>



MERCEDES BENZ A CLASS
amp VITO LCD PIXEL
INSTRUMENT CLUSTER
REPAIR
<https://www.freeadsz.co.uk/x-235064-z>



MERCEDES BENZ A CLASS
amp VITO LCD PIXEL
INSTRUMENT CLUSTER
REPAIR
<https://www.freeadsz.co.uk/x-235064-z>



MERCEDES BENZ A CLASS
amp VITO LCD PIXEL
INSTRUMENT CLUSTER
REPAIR
<https://www.freeadsz.co.uk/x-235064-z>



MERCEDES BENZ A CLASS
amp VITO LCD PIXEL
INSTRUMENT CLUSTER
REPAIR
<https://www.freeadsz.co.uk/x-235064-z>



MERCEDES BENZ A CLASS
amp VITO LCD PIXEL
INSTRUMENT CLUSTER
REPAIR
<https://www.freeadsz.co.uk/x-235064-z>



MERCEDES BENZ A CLASS
amp VITO LCD PIXEL
INSTRUMENT CLUSTER
REPAIR
<https://www.freeadsz.co.uk/x-235064-z>



MERCEDES BENZ A CLASS
amp VITO LCD PIXEL
INSTRUMENT CLUSTER
REPAIR
<https://www.freeadsz.co.uk/x-235064-z>

CONTACT US

CARTRONIX

CALL: 02392 265 986 or 02392 241412

ADDRESS: Unit 20The Parkwood Centre, Aston Road, Waterloooville, PO7 7HT

WEBSITE: www.cartronix.co.uk WARNING!!!! DON'T BUY A SECOND HAND UNIT IT IS A FALSE ECONOMY. YOUR CAR WILL NOT START. THE MILEAGE WILL BE INCORRECT AND YOU WILL NEED IT PROGRAMMING!!!

WITH OUR SERVICE WE FIX YOUR OWN UNIT AND THE CODING/MILEAGE REMAINS.