

# Audi 80 1994 2.0e Sport (400 GBP)



Location **South East, Berkshire**  
<https://www.freeadsz.co.uk/x-238104-z>

Audi 80 Sport 2.0E Saloon  
 1994 on M reg

172000 miles but will rise as its in daily use  
 Genuine sport with sports steering wheel/seats/spoiler etc, all original with no aftermarket parts fitted at all. It is in a pretty good condition considering its 20 years old, some dents/scratches but nothing too serious. The interiors in good condition too, with a little wear to the carpets and drivers seat bolster. Its in mechanically in good condition, it has never let me down, and I was considering taking it on our annual trip to Germany we do. With these having a galvanised chassis there is no major rust anywhere, except the small patch on the front wing. It has uprated pioneer front dash speakers and 6x9s that a previous owner cut into the rear doors and a Sony radio with aux in/cd/radio. There was no service history when I got it, just the most recent MOT certificate, which expires 29/05/2016. The only advisory on the last were wheel bearings on the rear, not expensive or difficult to change. All in all its a very honest car which with a days work it would be a fantastic daily or project.

When I got the car it had many problems which were not described which ive fixed:  
 I gave the car a full oil and filter change, new plugs, new fuel and cabin filters  
 when I got it the temp gauge wasnt working, so to fix it ive given it a full coolant flush and change, a new thermostat and radiator, and new temp sensors.  
 The fuel and temperature gauges are now fully working

fixed dodgy wiring going from car into bootlid  
 the boot lid now so  
 clicking noise when turning on full lock sometimes, suspected cv joint but not had time to investigate  
 the exhaust is knocking on the rear axle just needs adjusting I would have thought

Located in Horsham West Sussex RH12

the audi now has a radio. the original key has snapped in half therefore will need trailering/towing away. It also has been SORN'd as its no longer needed as its replacement is.



<https://www.freeadsz.co.uk/x-238104-z>

Audi 80 1994 2.0e Sport



<https://www.freeadsz.co.uk/x-238104-z>

Audi 80 1994 2.0e Sport




<https://www.freeadsz.co.uk/x-238104-z>

Audi 80 1994 2.0e Sport



<https://www.freeadsz.co.uk/x-238104-z>

Audi 80 1994 2.0e Sport



<https://www.freeadsz.co.uk/x-238104-z>

Audi 80 1994 2.0e Sport




<https://www.freeadsz.co.uk/x-238104-z>

Audi 80 1994 2.0e Sport



<https://www.freeadsz.co.uk/x-238104-z>

Audi 80 1994 2.0e Sport



<https://www.freeadsz.co.uk/x-238104-z>

Audi 80 1994 2.0e Sport



<https://www.freeadsz.co.uk/x-238104-z>

Audi 80 1994 2.0e Sport



<https://www.freeadsz.co.uk/x-238104-z>

Audi 80 1994 2.0e Sport