


Saab 9-3 2002 (150 GBP)



Location

South West, Hampshire<https://www.freeadsz.co.uk/x-318512-z>

I have had this car for two years and covered 50,000 miles in it in this time. Car currently has an Engine management light on the dash board and the high pressure power steering hose has a leak on it, hence why its for spares or repair. The good points All four tyres have about 5-6mm tread on them. Has about 3/4 of a tank of diesel in it. MOT is due at the start of May 2016 ;



<https://www.freeadsz.co.uk/x-318512-z>



<https://www.freeadsz.co.uk/x-318512-z>



<https://www.freeadsz.co.uk/x-318512-z>




<https://www.freeadsz.co.uk/x-318512-z>



<https://www.freeadsz.co.uk/x-318512-z>



<https://www.freeadsz.co.uk/x-318512-z>



<https://www.freeadsz.co.uk/x-318512-z>



<https://www.freeadsz.co.uk/x-318512-z>



<https://www.freeadsz.co.uk/x-318512-z>



<https://www.freeadsz.co.uk/x-318512-z>



<https://www.freeadsz.co.uk/x-318512-z>



<https://www.freeadsz.co.uk/x-318512-z>



<https://www.freeadsz.co.uk/x-318512-z>



<https://www.freeadsz.co.uk/x-318512-z>