

Audi A4 2007 (3,800 GBP)



Location **West Midlands, Herefordshire** https://www.freeadsz.co.uk/x-330273-z



Audi 2007 S- Line Quattro in Black with a full leather interior. The car has been in the family since the 2nd owner and has been very well looked after with only expected signs of wear and tear.

I have decided to peruse a career overseas and will soon no longer need the vehicle.

The car has recently had new tyres fitted & comes with the roof bars. The cambelt has already been changed.

The car is in overall very good condition. Many of the miles are made up of motorway miles and the high mileage doesn't effect car's performance.

The car has been triggering a engine management light fault for the last 6 months - Running to lean at idle (Not ticking over at high enough revs when idle) . I have had several Audi specialists diagnose the car, and they have said the car is running correctly at idle and to ignore the light.

In pursuit of turing the light of I have spent in excess of £500 by changing the following parts (including part number). I have also had several other valves and parts changed, and will update the Add when the Garage gets back to me with old invoices.

							-133-781L 	- Check \ - \(\oldsymbol{L} \) \(/alve With □ 2n'd 14 eren	Pipes igestion t	For Sets.			回談			温繁盛
Audi https://www.fre	73-2	Audi https://www.fre	https://www.fre 73-z	Audi	Audi https://www.fre	seme	garages have thing that is Lead at drives and	n't broker). Au	the hes://www.fre	e fault as I h	hess://www.fre	n spending Audi	gez 797z	on trying t Audi	h <mark>⊯</mark> os://www.fre	Audi
A4 eadsz.co.uk/		A4 eadsz.co.uk/	eadsz.co.uk/	A4	A4 eadsz.co.uk/	eadsz.co.uk/	Α4	eadsz.co.uk/	Α4	eadsz.co.uk/)	A4	eadsz.co.uk/)	A4	eadsz.co.uk/	Α4	eadsz.co.uk/	A4
2007		2007	<- 3302	2007	2007	< -3302	2007	<-3302	2007	k-3302	2007	<-3302	2007	<-3302	2007	<-3302	2007