




Our "Lifetime Warranty" ensures your repair will be covered for as long as you own your vehicle.

RENAULT SCENIC INSTRUMENT CLUSTER REPAIR (2003-2008) £89 The Renault Scenic Dash failure is quite a common fault. On this type of Odometer it is usually caused by internal components breaking down within the Instrument Cluster. The repair is carried out by fully qualified electronics engineers which involves stripping down the Instrument Cluster and replacing internal faulty components to rectify the problem. We do not offer "quick fix" we actually replace the faulty parts with new ones required for The Renault Scenic and your mileage reading will stay intact, so there is no need for mileage correction. Your Renault Scenic can be repaired at a fraction of the cost compared with the price of purchasing a new one. COMMON ISSUES Failing warning lights Renault Speedometer problems Flickering Cluster Complete power failure REMOVAL INSTRUCTIONS Unclip top surround downwards and towards you, unclip bottom surround upwards and towards you. Remove 2 plugs and then remove 2 x T20 torq screws. REPAIR PROCEDURE 1. Remove the cluster using the instructions on the website 2. Fill out and print our job form on our web site. If you don't have a printer please write the information manually including your post code on the outside of the box for our reference. 3. Sign the form, cut off the address label and secure to the front of the box. 4. We recommend sending via Royal Mail Special Delivery UK 5. When we have received the cluster and have repaired it, we will call you for payment via telephone WARRANTY AND TURN AROUND We offer a Lifetime Warranty (T&C's Apply), usually with a 24 hour turn around by post. If you come to our workshop in Waterlooville (near Portsmouth) we are able to offer a friendly 90 minute fast track service. (Appointment only) CONTACT US CARTRONIX CALL: 02392 265 986 02392 265 9...(click to reveal full phone number) or 02392 241412 02392 2414...(click to reveal full phone number) ADDRESS: Unit 20 The Parkwood Centre, Aston Road, Waterlooville, PO7

7HT WEBSITE: www.carttonix.co.uk WARNING!!!! DON'T BUY A SECOND HAND UNIT IT IS A FALSE



RENAULT SCENIC
INSTRUMENT CLUSTER
SPEEDO PANEL CLOCKS
REPAIR



RENAULT SCENIC
INSTRUMENT CLUSTER
SPEEDO PANEL CLOCKS
REPAIR

<https://www.freeadsz.co.uk/x-3318>
33-z



RENAULT SCENIC
INSTRUMENT CLUSTER
SPEEDO PANEL CLOCKS
REPAIR

<https://www.freedasz.co.uk/x-3318>
33-z



RENAULT SCENIC
INSTRUMENT CLUSTER
SPEEDO PANEL CLOCKS
REPAIR

<https://www.freeadsz.co.uk/x-3318>
33-z



RENAULT SCENIC
INSTRUMENT CLUSTER
SPEEDO PANEL CLOCKS
REPAIR

<https://www.freedasz.co.uk/x-3318-33-z>



RENAULT CLUSTER
INSTRUMENT SPEEDO PANEL CLOCKS
REPAIR

<https://www.freadsz.co.uk/x-3318>
33-z




RENAULT CLUSTER
INSTRUMENT SPEEDO PANEL CLOCKS
REPAIR

<https://www.freadsz.co.uk/x-3318>
33-z



INSTRUMENT CLUSTER
SPEEDO PANEL CLOCKS
REPAIR

<https://www.freeadsz.co.uk/x-3318>
33-z



**INSTRUMENT CLUSTER
SPEEDO PANEL CLOCKS
REPAIR**
<https://www.freedsz.co.uk/x-3318>
33-z



INSTRUMENT CLUSTER
SPEEDO PANEL CLOCKS
REPAIR

<https://www.freeadsz.co.uk/x-3318>
33-z