

## Vauxhall Combo 2002 1686cc (500 GBP)



Location Wales, South Glamorgan https://www.freeadsz.co.uk/x-433726-z



Van bought from builder, for parts, but on inspection found that the leaking water pump just needs to be replaced. But i don't have the time to do this, due to work commitments. Negatives No logbook water pump needs to be replaced windscreen has a crack, as shown in photo. Does not obscure vision, but needs to be replaced. Paintwork has chipped away on bonnet. Driver side floor panel is wet due to vauxhall design fault. Positives MOT EXPIRY = 1ST AUGUST 2016 TAX EXPIRY = 1ST NOVEMBER 2016 MILEAGE = 130559 Engine runs smoothly four very new tyres tank 1/4 full heated seats cage in back All fluids topped up Van cleaned in and out £500

Vauxhall Combo 2002 1686cc
https://www.freeadsz.co.uk/x-4337 26-z
Vauxhall Combo 2002 1686cc
https://www.freeadsz.co.uk/x-4337 26-z
Vauxhall Combo 2002 1686cc
https://www.freeadsz.co.uk/x-4337 26-z
Vauxhall Combo 2002 1686cc
https://www.freeadsz.co.uk/x-4337 26-z
Vauxhall Combo 2002 1686cc
https://www.freeadsz.co.uk/x-4337 26-z
Vauxhall Combo 2002 1686cc
https://www.freeadsz.co.uk/x-4337 26-z
Vauxhall Combo 2002 1686cc
https://www.freeadsz.co.uk/x-4337 26-z
Vauxhall Combo 2002 1686cc
https://www.freeadsz.co.uk/x-4337 26-z
Vauxhall Combo 2002 1686cc
https://www.freeadsz.co.uk/x-4337 26-z
Vauxhall Combo 2002 1686cc
https://www.freeadsz.co.uk/x-4337 26-z