



TOYOTA AURIS INSTRUMENT CLUSTER DASH REPAIR 2006 - 2016

£150

The Toyota Auris dash failure is quite a common fault and on this type of odometer it is usually caused by internal components breaking down within the instrument cluster, we can repair this problem by replacing the damaged components with more reliable ones.

The Toyota Aurid speedo repair is carried out by fully qualified technicians and can be done at a fraction of the cost of a new one.

COMMON FAULTS

INDICATOR LIGHTS NOT ILLUMINATING
LCD SCREEN FAULTY
GAUGES FAILING
BACK LIGHTING FAILURE
TOTAL FAILURE

REPAIR PROCEDURE

1. Remove the cluster using the instructions on the website.

2. Fill in and print off the form on our Web Site. You do not need a printer please send the information to us by email including your name and address of the box for correspondence.

3. Sign the form, cut off the address label and secure to the front of the box.

4. We recommend sending via Royal Mail Special Delivery UK.

5. When we have received the cluster and have repaired it we will call you for payment via telephone.

WARRANTY AND TURN AROUND



TOYOTA AURIS
INSTRUMENT CLUSTER
DASH SPEEDOMETER
REPAIR



TOYOTA AURIS
INSTRUMENT CLUSTER
DASH SPEEDOMETER
REPAIR

<https://www.freadsz.co.uk/x-4993>
66-z



TOYOTA AURIS
INSTRUMENT CLUSTER
DASH SPEEDOMETER
REPAIR


<https://www.freeadsz.co.uk/x-4993>

66-z



TOYOTA AURIS
INSTRUMENT CLUSTER
DASH SPEEDOMETER
REPAIR


<https://www.freedasz.co.uk/x-4993>
66-z




WARRANT



<https://www.tandfonline.com/doi/full/10.1080/0013790X.2023.2234444>
 63-72



TOYOTA
AURIS
CLUSTER
INSTRUMENT
DASH
SPEEDOMETER
REPAIR



TOYOTA AURIS
INSTRUMENT CLUSTER
DASH SPEEDOMETER
REPAIR

we will call UK

<https://www.freedsz.co.uk/x-4993>



TOYOTA AURIS
INSTRUMENT CLUSTER
DASH SPEEDOMETER
REPAIR



TOYOTA AURIS
INSTRUMENT CLUSTER
DASH SPEEDOMETER
REPAIR

We offer a Lifetime Warranty (T&C's Apply), usually with a 24 hour turn around by post.

If you come to our workshop in Waterloooville (near Portsmouth) we are able to offer a friendly 90 minute fast track service. (Appointment only)

CONTACT US

CARTRONIX

CALL: 02392 265 986 02392 265 9...(click to reveal full phone number) or 02392 241412 02392 2414...(click to reveal full phone number)

ADDRESS: Unit 20 The Parkwood Centre, Aston Road, Waterloooville, PO7 7HT

WEBSITE: www.cartronix.co.uk

WARNING!!!! DON'T BUY A SECOND HAND UNIT IT IS A FALSE ECONOMY. YOUR CAR WILL NOT START. THE MILEAGE WILL BE INCORRECT AND YOU WILL NEED IT PROGRAMMING!!!

WITH OUR SERVICE WE FIX YOUR OWN UNIT AND THE CODING/MILEAGE REMAINS.