

## TOYOTA AURIS INSTRUMENT CLUSTER DASH SPEEDOMETER REPAIR



Location **South West, Hampshire** https://www.freeadsz.co.uk/x-499366-z



£150

The Toyota Auris dash failure is quite a common fault and on this type of odometer it is usually caused by internal components breaking down within the instrument cluster, we can repair this problem by replacing the damaged components with more reliable ones.

The Toyota Aurid speedo repair is carried out by fully qualified technicians and can be done at a fraction of the cost of a new one.

**COMMON FAULTS** 

INDICATOR LIGHTS NOT ILLUMINATING LCD SCREEN FAULTY GAUGES FAILING BACK LIGHTING FAILURE TOTAL FAILURE





We offer a Lifetime Warranty (T&C's Apply), usually with a 24 hour turn around by post.

If you come to our workshop in Waterlooville (near Portsmouth) we are able to offer a friendly 90 minute fast track service. (Appointment only)

**CONTACT US** 

**CARTRONIX** 

CALL: 02392 265 986 02392 265 9...(click to reveal full phone number) or 02392 241412 02392 2414...(click to reveal full phone number)

ADDRESS: Unit 20 The Parkwood Centre, Aston Road, Waterlooville, PO7 7HT

WEBSITE: www.cartronix.co.uk

WARNING!!!! DON'T BUY A SECOND HAND UNIT IT IS A FALSE ECONOMY. YOUR CAR WILL NOT START. THE MILEAGE WILL BE INCORRECT AND YOU WILL NEED IT PROGRAMMING!!!

WITH OUR SERVICE WE FIX YOUR OWN UNIT AND THE CODING/MILEAGE REMAINS.