

# Land Rover Discovery 1998 (600 GBP)



Location **Scotland, Renfrewshire**  
<https://www.freeadsz.co.uk/x-509408-z>

For sale is my disco 1 It currently has no mot or tax. Just needs a good clean as been sitting a month or so.

Automatic (Bluetooth stereo will be Removed unless I get full price)

MAY BREAK IF ENOUGH INTEREST SOLID CHASSIS Leather Electric seats, heated front window, full electric windows and sunroofs (don't leak)

Heated seats, remote central locking, Starts and drives perfect.

It has a slight fault with transfer box (output bearing). There is a box there to replace or change the bearing and seal. Lost count how much money I have spent on her. Twin battery setup with split charger.

Genuine safari snorkel and all sealed correctly.

Performance air filter (lifetime warranty)

Voltage meters pods (need we tidy up now)

Rear door ladder

Roof lights (all wired up and run on second battery)

New heavy duty terifirma rear shocks

New front super Gaz shocks

Front chrome nudge bar (1 front spotlight broken) (gate swung open and hit it)

Brand new speakers in all doors and rear door amp.

4 brand new cooper all terrain at3 tyres 1000 miles ago (worth over £450)

Heavy duty front steering arm and ball joints

New swivel ball, seals, bearings



<https://www.freeadsz.co.uk/x-509408-z>  
**Land Rover Discovery 1998**



<https://www.freeadsz.co.uk/x-509408-z>  
**Land Rover Discovery 1998**



<https://www.freeadsz.co.uk/x-509408-z>  
**Land Rover Discovery 1998**



<https://www.freeadsz.co.uk/x-509408-z>  
**Land Rover Discovery 1998**

2 front Cv joints  
 1 front shock 1000 miles ago  
 2 new speakers  
 2 new speakers  
 1 new for lock  
 Tracking done

New lift pump  
 brand new battery (5 year warranty)  
 New front propshaft and joints.  
 Front and rear disks and pads  
 2 new front galvanised spring seats  
 Front and rear shocks all polly pushed Has had welding to body previously for last mot but shouldn't

Front and rear shocks all polly pushed Has had welding to body previously for last mot but shouldn't



<https://www.freeadsz.co.uk/x-509408-z>  
**Land Rover Discovery 1998**




<https://www.freeadsz.co.uk/x-509408-z>  
**Land Rover Discovery 1998**



<https://www.freeadsz.co.uk/x-509408-z>  
**Land Rover Discovery 1998**



<https://www.freeadsz.co.uk/x-509408-z>  
**Land Rover Discovery 1998**



<https://www.freeadsz.co.uk/x-509408-z>  
**Land Rover Discovery 1998**

---

require any more. Loads of spare parts if.