HOTPOINT WASHING MACHINE PARTS Ready Stripped from unit Complete (25 GBP)



East Midlands, Northamptonshire Location https://www.freeadsz.co.uk/x-551104-z



Have stripped a Hotpoint WD440 1400. It had thrown the belt and found the Drum Bearings to be faulty. Rather than dispose to incoming supplier I have stripped parts. All other parts were in working order and rather than repair - replace bearing Installed and updated. Selling individually or as "job lot" Still have casing and drum. All components are away from the unit and stored for collection. Door, panels, motor, pump etc everything. Pricing at job lot or first sold part to reach minimum pprice . EVERYTHING IS THERE- COMPLETE. components



























https://www.freeadsz.c 04-z	Stripped f
w.freea	8
dsz.c	m unit

s://www.freeadsz.co.uk/x-551	HOTPOINT V.CHINE PARTS pped from unit
o.uk/x-551	WASHIN Read Comple



https://www.freeads 04-z	Stripped
w.freea	from
l ds	







