

FAULTY Big Shot Express electric die cutting amp embossing machine. Not working.



Location **East of England, Bedfordshire**
<https://www.freeadsz.co.uk/x-555869-z>



FAULTY Big Shot Express electric die cutting & embossing machine for spares or repair.

Not working although it does power through without the 'sandwich', it seems as though there's not enough power to run it with the 'sandwich' in.
Might need new motor or a thorough clean out inside but I've just ordered a new machine.

Includes Essentials Platform, instructions & Wafer Thin Die Adapter plus 1 Provo Craft die (heart, star, brackets, hashtag, @ 9 & 0) & 2 very small Sizzix embossing folders (a pair of Elf legs & a champagne glass).

Cutting plates not included, only what's mentioned above.

These extras alone must be worth the £10 so if you can get the machine repaired to run properly, you have a real bargain. :)

Collection from Hodge Lea, MK12. (Not).



FAULTY Big Shot Express electric die cutting amp embossing machine. Not working. Sparesrepair. <https://www.freeadsz.co.uk/x-555869-z>



FAULTY Big Shot Express electric die cutting amp embossing machine. Not working. Sparesrepair. <https://www.freeadsz.co.uk/x-555869-z>



FAULTY Big Shot Express electric die cutting amp embossing machine. Not working. Sparesrepair. <https://www.freeadsz.co.uk/x-555869-z>



FAULTY Big Shot Express electric die cutting amp embossing machine. Not working. Sparesrepair. <https://www.freeadsz.co.uk/x-555869-z>



FAULTY Big Shot Express electric die cutting amp embossing machine. Not working. Sparesrepair. <https://www.freeadsz.co.uk/x-555869-z>



FAULTY Big Shot Express electric die cutting amp embossing machine. Not working. Sparesrepair. <https://www.freeadsz.co.uk/x-555869-z>



FAULTY Big Shot Express electric die cutting amp embossing machine. Not working. Sparesrepair. <https://www.freeadsz.co.uk/x-555869-z>



FAULTY Big Shot Express electric die cutting amp embossing machine. Not working. Sparesrepair. <https://www.freeadsz.co.uk/x-555869-z>



FAULTY Big Shot Express electric die cutting amp embossing machine. Not working. Sparesrepair. <https://www.freeadsz.co.uk/x-555869-z>



FAULTY Big Shot Express electric die cutting amp embossing machine. Not working. Sparesrepair. <https://www.freeadsz.co.uk/x-555869-z>