

BMW 1 Series 2005 (1,550 GBP)



Location Wales, West Glamorgan https://www.freeadsz.co.uk/x-562249-z



Drives faultless had it 2 years no problems, air bag light on due to seat belt sensor broke 35£ on eBay, all dent and scratch in photos, bonnet cable nipped snapped so needs plyers to open common.

線網線	BMW	_	Series	2005
	https://www. 49-z	.freea	dsz.co.uk/x	:-5622
	BMW	<u> </u>	Series	2005
	https://www. 49-z	.freea	dsz.co.uk/x	5622
機構	BMW	_	Series	2005
	https://www.	.freea	dsz.co.uk/x	5622
機構	BMW	_	Series	2005
	https://www. 49-z	.freea	dsz.co.uk/x	:-5622
	BMW	_	Series	2005
	https://www. 49-z	.freea	dsz.co.uk/x	:-5622
	BMW	_	Series	2005
	https://www.	.freea	dsz.co.uk/x	:-5622
- 7	BMW	_	Series	2005
	https://www. 49-z	.freea	dsz.co.uk/x	5622
	BMW	_	Series	2005
	https://www. 49-z	.freea	dsz.co.uk/x	:-5622
	BMW	_	Series	2005
	https://www. 49-z	.freea	dsz.co.uk/x	-5622
	BMW	_	Series	2005
	https://www. 49-z	.freea	dsz.co.uk/x	5622