










Volvo S80 1999 (300 GBP)



Location **South East, East Sussex**
<https://www.freeadsz.co.uk/x-329350-z>



I HAVE OWNED THIS CAR FOR THE LAST 6 YEARS AND CAN SAY IT HAS BEEN THE BEST CAR I HAVE HAD, AND VERY RILIALE AND IT IS NOW IN NEED OF SOME TLC FOR MOT THE BAD BITS: A COUPLE OF SMALL DENTS, ONE IN PASSANGER DOOR AND ONE ON THE FRONT WING THERE IS A KNOCKING ON THE FRONT (TRACK ROD END I THINK) A SMALL STRIP OF SURFACE RUST ON DRIVERS DOOR (HAS BEEN THERE SINCE I'VE OWNED THE CAR, NOT STRUCTURAL) THE REAR DOOR HAS JUST STARTED TO MAKE A NOISE WHEN LOCKING/UNLOCKING, I BELIEVE THIS IS JUST THE LOCKING SOLENOID STARTING TO MISBEHAVE HAVING SAID THE ABOVE THE INTERIOR IS IN GOOD CONDITION AND ENGINE AND GEARBOX ARE MECHANICALLY SOUND AND STILL RUNS SILKY SMOOTH ANY QUESTIONS, PLEASE DO NOT HESITATE TO CALL

 https://www.freeadsz.co.uk/x-329350-z <div>VolvoS801999</div>	 https://www.freeadsz.co.uk/x-329350-z <div>VolvoS801999</div>	 https://www.freeadsz.co.uk/x-329350-z <div>VolvoS801999</div>	 https://www.freeadsz.co.uk/x-329350-z <div>VolvoS801999</div>	 https://www.freeadsz.co.uk/x-329350-z <div>VolvoS801999</div>	 https://www.freeadsz.co.uk/x-329350-z <div>VolvoS801999</div>	 https://www.freeadsz.co.uk/x-329350-z <div>VolvoS801999</div>	 https://www.freeadsz.co.uk/x-329350-z <div>VolvoS801999</div>	 https://www.freeadsz.co.uk/x-329350-z <div>VolvoS801999</div>	 https://www.freeadsz.co.uk/x-329350-z <div>VolvoS801999</div>
--	---	---	---	--	---	---	---	---	---