

Used Electric Ceramic Hob SparesRepairs (40 GBP)



Location **London, London**
<https://www.freeadsz.co.uk/x-501918-z>



Hotpoint Model # 55538 R , broken glass but 4 Hob elements working with safety indicators. 1 off 4 simmerstats not working. Bought in 2012 clean no scratches. See Pictures.Buyer Collects. ;



Used Electric Ceramic Hob
SparesRepairs

<https://www.freeadsz.co.uk/x-501918-z>



Used Electric Ceramic Hob
SparesRepairs

<https://www.freeadsz.co.uk/x-501918-z>



Used Electric Ceramic Hob
SparesRepairs

<https://www.freeadsz.co.uk/x-501918-z>



Used Electric Ceramic Hob
SparesRepairs

<https://www.freeadsz.co.uk/x-501918-z>



Used Electric Ceramic Hob
SparesRepairs

<https://www.freeadsz.co.uk/x-501918-z>



Used Electric Ceramic Hob
SparesRepairs

<https://www.freeadsz.co.uk/x-501918-z>




Used Electric Ceramic Hob
SparesRepairs

<https://www.freeadsz.co.uk/x-501918-z>



Used Electric Ceramic Hob
SparesRepairs

<https://www.freeadsz.co.uk/x-501918-z>



Used Electric Ceramic Hob
SparesRepairs

<https://www.freeadsz.co.uk/x-501918-z>



Used Electric Ceramic Hob
SparesRepairs

<https://www.freeadsz.co.uk/x-501918-z>