

Mercedes Sprinter 311Cdi LWB Diesel 2009 (3,400 GBP)



Location **Yorkshire and the Humber, North Humberside**
<https://www.freeadsz.co.uk/x-516753-z>

About the van; 16ft Dropwell Luton

First registered 29.05.2009 and comes with full service history. Vehicle is fitted with a brand new GRP body by JC Payne. The interior of the Luton body is fitted with furniture tie rails and LED lighting. To the rear there is a drop down walk in tailboard with anti-slip wooden strips. Very important this as if you have ever had this type of walk in board not fitted with the wooden strips you will know how slippery they can be in the wet. Above the tailboard are two barn doors. The rear lights have been specially recessed into the rear pillars for protection.


Internal body length is 16ft (from back of cab to rear doors)

Total volume is around an amazing 950 cubic feet


Specification;
 One Owner
 HPI Clear
 6 Speed
 Anti-Lock Braking System
 Compact Disc Player
 Driver's Airbag
 Electric Windows
 Full Service History




Mercedes Sprinter 311Cdi
LWB Diesel 2009



Mercedes Sprinter 311Cdi
LWB Diesel 2009



Mercedes Sprinter 311Cdi
LWB Diesel 2009




Mercedes Sprinter 311Cdi
LWB Diesel 2009


Immobiliser
 Full Service History
 HPI Clear
 6 Speed
 Anti-Lock Braking System
 Compact Disc Player
 Driver's Airbag
 Electric Windows
 Full Service History




Mercedes Sprinter 311Cdi
LWB Diesel 2009



Mercedes Sprinter 311Cdi
LWB Diesel 2009



Mercedes Sprinter 311Cdi
LWB Diesel 2009



Mercedes Sprinter 311Cdi
LWB Diesel 2009



Mercedes Sprinter 311Cdi
LWB Diesel 2009

Overall Height 10ft 10ins
Overall Width 7ft 7ins
Overall Length 24ft 3ins

Internal
Internal Length 16ft
Internal Width 6ft 10ins
Internal Height 7ft 7ins

Luton (part above cab)
Luton Width 6ft 10ins
Luton Height 2ft 11ins
Luton Length 3ft 3ins

Dropwell (step at rear)
Drop Well Height 9ft 2ins
Drop Well Width 6ft 10ins
Drop Well Length 3ft 11ins

Condition – Interior:

The interior is in lovely condition.

The driver's and passenger seats are in good condition. Everything is very clean.

Service History:

Vehicle comes with maintenance history documentation detailing all services and work carried out from.